

Working parameters	Remote monitoring	None
	Remote monitoringWaterproof requirement	None
	work environment	Operating temperature: 0 ° C to + 45 ° c operating humidity: 5% to 90%
	Power Supply	AC110~240V 60HZ
	power	140W